Before the FEDERAL COMMUNICATIONS COMMISSION Washington, D.C. 20554

In the Matter of)
Connoisseur Media of Erie, LLC Registrant of Antenna Structure ASR # 1036227 Erie, Pennsylvania) File No. EB-10-PA-0264) NOV No. V201132400003
)

To: District Director, Philadelphia Office, Northeast Region, Enforcement Bureau

RESPONSE TO NOTICE OF VIOLATION

Connoisseur Media of Erie, LLC ("Connoisseur"), owner of tower structure Antenna

Structure Registration Number ("ASRN") 1036227, hereby responds to the Commission's Notice of

Violation ("NOV") released October 14, 2010. As detailed below, proper signage displaying the

correct ASRN was affixed to the tower and readily visible at the base of the antenna structure at all

times. Accordingly, the tower site was in compliance with the Commission's requirement that the

registration number of the tower be posted at the site. In addition, a second sign at the site provided
the same information at the fence line, before entering the tower site. While the final digit of the

ASRN mounted on the fence surrounding the tower site had been faded by the weather,

Connoisseur has now replaced that sign and resolved the issue. Accordingly, as the tower

maintained proper signage at all relevant times, and Connoisseur immediately fixed the minor issue
with the second sign on the fence, Connoisseur submits that no further action by the Commission is
necessary in this matter.

In its NOV released October 14, 2010, the Commission raised one potential violation of the Rules involving the ASRN posted at the broadcast tower site owned and operated by Connoisseur in Erie, Pennsylvania. According to the NOV, an agent of the Commission's Philadelphia Office

visited the Erie tower site on September 23, 2010 and observed a sign containing ASR number 1036226, rather than the correct registration number 1036227. Pursuant to Section 17.4(g) of the Commission's rules the Antenna Structure Registration Number of the tower "must be displayed in a conspicuous place so that it is readily visible near the base of the antenna structure. Materials used to display the Antenna Structure Registration number must be weather-resistant and of sufficient size to be easily seen at the base of the antenna structure." In this case, the Erie tower site actually has two such signs, the first affixed to the tower itself, and the second mounted on the fence surrounding the tower site. With respect to the sign affixed to the tower itself, that sign displays the correct ASRN – 1036227 – and was not mentioned in the NOV. That sign is readily visible near the base of the antenna structure, consistent with the Commission's Rules.²

With respect to the second, additional sign mounted on the fence surrounding the tower site, the weather had faded a previous correction made to that sign, such that the final digit of the ASRN appeared to be a "6" rather than a "7". Although the sign on the fence had previously been corrected to read "1036227", as a result of time and weather, the painted correction to the final digit of the ASRN had sufficiently faded so that both the "7" and the incorrect "6" were visible. Following his visit to the tower, the FCC field agent contacted Connoisseur by telephone to inform it that the final digit on the fence-mounted sign was incorrect, as it displayed a "6" rather than a "7". Acting on that information, Connoisseur immediately removed the fence-mounted sign the same day as the agent's visit, September 23, 2010. Connoisseur has now replaced that sign with a brand

⁴⁷ C.F.R. § 17.4(g).

The Commission's Letter simply states that the agent observed the incorrect ASRN "posted at the base of the antenna structure", but it appears that the sign observed by the agent was the sign affixed to the fence at the tower site, and not the sign on the base of the tower itself.

new, weather-resistant sign, thereby resolving the issue. No other potential violations were conveyed to Connoisseur in the agent's telephone call, nor raised by the recent NOV.

Given that the correct ASR number was posted on the sign affixed to the tower itself, proper signage was maintained at the tower site at all times consistent with Section 17.4(g) of the Commission's Rules. Moreover, Connoisseur immediately removed and took steps to replace the second sign on the fence as soon as it was informed of the issue. Therefore, Connoisseur submits that no violation of the Commission's Rules has occurred, and any potential confusion arising from the second, fence-mounted sign has been resolved and will not reoccur as the sign has already been entirely replaced with a new, weather-resistant sign. Accordingly Connoisseur submits that no further Commission action is necessary in this matter. The foregoing is true and correct to the best of my knowledge, information, and belief.

Respectfully submitted,

CONNOISSEUR MEDIA OF ERIE, LLC

Mothael O. Paris -

Michael O. Driscoll

Member of CM Broadcast Management, LLC, the Sole Managing Member of Connoisseur Media, LLC, the sole Member of Connoisseur Media of Erie, LLC

Connoisseur Media of Erie, LLC 136 Main Street Suite 202 Westfield, CT 06880 (207) 227-1978

Date: October 22, 2010

Before the Federal Communications Commission Washington, D.C. 20554

In the Matter of)
Connoisseur Media of Erie, LLC Registrant of Antenna Structure ASR # 1036227 Erie, Pennsylvania) File No. EB-10-PA-0264
) NOV No. V201132400003
)

NOTICE OF VIOLATION

Released: October 14, 2010

By the District Director, Philadelphia Office, Northeast Region, Enforcement Bureau:

- This is a Notice of Violation ("Notice") issued pursuant to Section 1.89 of the Commission's Rules¹ to Connoisseur Media of Erie, LLC, the owner of antenna structure # 1036227 in Erie, Pennsylvania.
- 2. On September 23, 2010, an agent of the Commission's Philadelphia Office inspected antenna structure # 1036227 located in Erie, Pennsylvania and observed the following violation:

47 C.F.R. § 17.4(g): "The Antenna Structure Registration Number must be displayed in a conspicuous place so that it is readily visible near the base of the antenna structure. Materials used to display the Antenna Structure Registration number must be weather-resistant and of sufficient size to be easily seen at the base of the antenna structure." At the time of inspection, the agent observed that the incorrect Antenna Structure Registration ("ASR") number (1036226) was posted at the base of the antenna structure.

3. Pursuant to Section 403 of the Communications Act of 1934, as amended,² and Section 1.89 of the Commission's Rules, Connoisseur Media of Erie, LLC must submit a written statement concerning this matter within twenty (20) days of release of this Notice. The response must fully explain each violation, must contain a statement of the specific action(s) taken to correct each violation and preclude recurrence, and should include a time line for completion of pending corrective actions. The response must be complete in itself and signed by a principal or officer of the tower owner. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

⁴⁷ C.F.R. § 1.89.

² 47 U.S.C. § 403.

Federal Communications Commission Philadelphia Office One Oxford Valley Building, Suite 404 2300 East Lincoln Highway Langhorne, Pennsylvania 19047

- 4. This Notice shall be sent to Connoisseur Media of Erie, LLC at its address of record.
- 5. The Privacy Act of 1974³ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁴

FEDERAL COMMUNICATIONS COMMISSION

anced Chambraudi son

Gene J Stanbro District Director Philadelphia Office Enforcement Bureau Northeast Region Enforcement Bureau

³ P.L. 93-579, 5 U.S.C. § 552a(e)(3).

⁴ 18 U.S.C. § 1001 et seq.